

RDX QuikStor SATA III Release Notes

RDX QuikStor SATA III Firmware Version 0242

FW version: 0242

Fixes:

- Fixed issue where host computer cannot detect the RDX QuikStor SATA III dock when dock is configured in 3G/6G mode. The SATA III dock now detects when the host is unable to reconnect after switching to 3G/6G mode. When reconnect fails the dock automatically drops back to 1.5G/3G mode.
- Added LED error condition when SATA III dock firmware file is corrupt. LED color is amber to notify the user.
- Fixed issue where the SATA III dock will drop off the host bus when read or write errors are detected.